




PIA-2000 DIRT COUNTER SCREENS



SET THRESHOLD
 PAPER BACKGROUND
 GRAY LEVEL = 42
 REFLECTANCE = 84 %
 DIRT THRESHOLD
 GRAY LEVEL = 62
 REFLECTANCE = 76 %
 X=0.88 Y=0.63 I= 64
 +/- TO CHANGE DIRT THRESHOLD
 SHIFT +/- TO STOP SCREEN UPDATE
 ALT-ARROWS MOVES ZOOM BOX
 ARROWS ALONE MOVE CROSS HAIR
 SPACE BAR TO SET THRESH TO WHAT I=
 1-9 CHANGE STEP
 ENTER TO BEGIN TEST
 ESC FOR MAIN MENU
 F1 TO DO ZOOM SCAN



SET THRESHOLD
 PAPER BACKGROUND
 GRAY LEVEL = 53
 REFLECTANCE = 79 %
 DIRT THRESHOLD
 GRAY LEVEL = 75
 REFLECTANCE = 71 %
 X=0.17 Y=0.13 I= 53
 +/- TO CHANGE DIRT THRESHOLD
 SHIFT +/- TO STOP SCREEN UPDATE
 ALT-ARROWS MOVES ZOOM BOX
 ARROWS ALONE MOVE CROSS HAIR
 SPACE BAR TO SET THRESH TO WHAT I=
 1-9 CHANGE STEP
 ENTER TO BEGIN TEST
 ESC FOR MAIN MENU
 F1 TO DO ZOOM SCAN



PAPER BACKGROUND
 GRAY LEVEL = 53
 REFLECTANCE = 79 %
 DIRT THRESHOLD
 GRAY LEVEL = 75
 REFLECTANCE = 71 %
 CURRENT SAMPLE 1
 PPM = 329.36
 SQ.MM = 5.048
 QUICK KEYS
 ENTER TO TEST
 ESC FOR REPORT AND MAIN MENU
 Alt-F12=DELETE TEST

APPLIED VISION SYSTEMS

LO / HI	COUNT	SQ.MM.	PPM	
0.02	0.03	66	1.226	79.97
0.04	0.10	28	1.698	110.75
0.15	0.80	9	2.125	138.64
1.00	>5.5	0	0.000	0.00
ALL SIZES	103	5.048		329.36

PAPER THRESHOLD = 53
 DIRT THRESHOLD = 75
 DPI = 400
 Alt-F12 TO DELETE LAST TEST

1 SAMPLE(S) 0.02 SQ.M.			
SIZE	QTY	SIZE	QTY
.005	0	0.06	9
.006	0	0.07	3
.007	0	0.08	2
.008	0	0.09	1
.009	0	0.10	1
0.01	0	0.15	2
0.02	55	0.20	2
0.03	11	0.25	1
0.04	2	0.30	3
0.05	10	0.40	1

ENTER TO PRINT / ESC FOR MAIN MENU
 F2 TOGGLE REPORT SCREEN

